

640 Indicator



Simple Operation

- ZERO key zeros the scale, PRINT key transfers weight data to printer, computer, Gross/Tare/Net
- G/N key allows viewing of either gross or net weights. TARE key is useful for temporary "zeroing" of the scale

Motion Filtering

- Enhanced dual "harmonizer" filtering settles down weight display for easy viewing. Ideal for filtering excess motion on mixers and livestock applications

Memory Accumulators

- 100 six-character alpha-numeric accumulator channels. Useful in identifying fields, seed type, livestock groups or amounts of recipes batched and or fed

800.582.3175

A general purpose indicator which provides simple, yet accurate and reliable weighing used on mixers, grain carts (grain chasers), livestock scales, feed bins, weigh carts and many more applications.



2403 26th Ave
Central City, NE 68826
ccscales.com